



ArcGIS Web Map



5/18/2026, 8:31:15 AM

1:4,408

SV_SERVICEPOINTGAS_UN	Elbow	CP Anode	Distribution Main
Service Line	End Cap	Locate Ball	Coated Steel,60
Coated Steel,In Service	Reducer	Emergency Valves	Plastic PE,60
Plastic PE,In Service	Tee	Yes	Abandoned Distribution Main
Noncontrollable Fittings	Transition	No Stations	Abandoned Service Line
Coupling	Weld	Regulator Station	COS Pavement Projects
Riser			
Plastic Fusion			



Vantor, Esri Community Maps Contributors, St. Louis County (MN), MN Dept Natural Resources, © OpenStreetMap, Microsoft, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA, USFWS